imaet PRO Version 11 Release Notes

Software

Bugs & Fixes

- Picture upload function on Client Profile restored
- Error when uploading picture on Client Profile fixed
- Glitch when running Comprehensive Database Scan in Allergen Panel fixed
- Invalid Variant Type Conversion error in Allergen Panel fixed
- Error in Body Biofield Panel and scan running continuously fixed
- Misspellings in various databases corrected

New Features & Improvements

- Ability to save Allergen Panel scans restored
- Homeopathic Panel redesigned and reinstated
- Panel Info Pages now available: Chakra, Prayers, Aura Color Descriptions, Dental, Detox and Nutritional

Box and Accessories

- New exterior graphics on the interface box
- Increased grounding in the interface box
- Added EMF protection in the interface box
- Two single-channel banana plug ports added to the interface box
- Improved LED lights in the interface box

Minimum System Requirements

- Windows 10 or later
- 8 Gigabytes RAM
- i5 Processor
- 512 Gigabytes of Internal Memory

Known Issues & Limitations

- Panel Info button is missing on the Body Biofield Panel
- Bio-Scan on Geopathic Panel continues to display after scan is completed. Does not affect functionality
- Anti-virus or anti-malware software running during use can cause malfunction
- Pending Windows Updates and driver updates can cause malfunction
- Opening the program while it is already running, creating multiple instances of the program, causes malfunction

BioGen Technologies, Inc.

Owner: Dr. Bernard Straile

See our Recommended [Device Best Practices](#) for optimal performance